

Quick Guide to Installing HallMonitor 4

WARNING: DO NOT CONNECT THE SENSOR TO POWER DURING INSTALLATION

1. Prepare the power source and run any necessary cables to the sensor.
2. Mount the wall bracket at a minimum height of 3 metres and a maximum of 4 metres.
3. Attach the sensor, including the spacer, to the wall bracket and secure the screws.
4. Adjust the sensor approximately 15 degrees downward in the vertical plane and centre it towards the area where activity takes place.

